⊾Date: Job Number Prsht Rev. First Issue

Thursday, 06/11/2008 3:46:52 PM

Julie Dawson

## **Process Sheet**

Customer

: CU-DAR001 Dart Helicopters Services

: 43264

**Estimate Number** : 12791

P.O. Number

This Issue : 06/11/2008

: NC

: 11

Previous Run

: 42237

Type

S.O. No. :

: SMALL /MED FAB

Part Number

**Drawing Name** 

: D35661 . D3566 REV C

: GASKET

**Drawing Number Project Number** 

: N/A

: C

**Drawing Revision** 

Material

**Due Date** : 17/11/2008

Qty:

20 Um:

Each

Checked & Approved By

Comment

Written By

New Issue 07-03-08 ec : Est Rev:A

Est Rev:B Added Drain Holes 07-07-09 JLM

Est Rev:C As per Rev C 07-09-09 JLM Verified By:EC

**Additional Product** 

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

MNEO60S063

NEOPRENE SHEET 0.063

MAT NOT PILLED

Comment: Qty.:

0.9566 sf(s)/Unit

19.1310 sf(s) Total:

**NEOPRENE SHEET 0.063** 

109664

R 8-4-11

2.0

WATER JET



Comment: FLOW WATER JET

1-Cut as per Dwg D3566

Dwg Rev:\_ Prog Rev:

IR 8-11-11

2-Deburr if necessary

18841-11

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



K8-11-11

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0 QC8

SECOND CHECK



08/11/11



Comment: SECOND CHECK

5.0

3.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:



## **Dart Aerospace Ltd**

	. oopaoo								
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			-10						
Part No	:	PAR #:	Fault Categ	gory:	NCR: Yes	No DQ	⊥ A:	Date:	
	Re	esolution:	Disposition	1:	QA: N/C	Closed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	R)			<del></del>
DATE	OTED	Description of NC	ļ	Corrective Action Section B		Verific	rification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector

NOTE: Date & initial all entries

Date:

Thursday, 06/11/2008 3:46:52 PM

User: `

Julie Dawson

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: GASKET

Job Number: 43264

Part Number: D35661

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21



FINAL INSPECTION/W/O RELEASE

mF 08-11-12

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



Dart Ae	rospace L	td						
W/O:			W	ORK ORDER CHANGE	ES			
DATE	STEP	PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes	No <b>DQA:</b>	Date: _	
Resolution:		olution:	Disposition	on:	_ QA: N/C Closed: Date			· 
NCR:		\	WORK ORD	ER NON-CONFORMA	NCE (NCR	)		
		Description of NC Corrective Action Se				Verification	Approval	Approval
DATE	STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector	

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	43264
Description: Gasket	Part Number:	D3566-1
Inspection Dwg: D3566 Rev: C		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
3.10	+/-0.030	3,110	×			
18.00	+/-0.030	18,00	<b>X</b>			
12.10	+/-0.030	19.10	<b>&gt;</b>			
2.43	+/-0.030	2,432	*			
6.00	+/-0.030	6.003	×			
1.40	+/-0.030	1,36	Þ			
0.30	+/-0.030	33	æ			
0.30	+/-0.030	.313				-
0.063	+/-0.010	,059	8			
Ø0.188	+0.005/-0.001	193	*			
				7		

Measured by: Audited by: M Prototype Approval: N/A

Date: Prototype Approval: N/A

Date: N/A

Rev	Date	Change	Revised by	Approved
Α	07.03.14	New Issue	KJ/JLM	
В	07.07.18	Dimensions updated per Dwg Rev. B	KJ/JLM	
С	07.09.26	Dwg Rev updated	KJ/EC/DD	12

HERT AND COMPANDED COPPOSITION OF COLUMN TO AMOUNT MEAN WITHOUT NOTE E

